

B1  
Control

test. However, the shrinkages can be more. For example, the machine direction shrinkage can be at least 5%, more particularly at least 6%, and as much as 7% or more, for example more than 8%. The transverse direction shrinkages can, for example, be at least 5%, more particularly at least 6%, and as much as 7% or more, for example more than 8%.

**IN THE CLAIMS:**

*Please cancel Claim 11 without prejudice and without dedication or abandonment of the subject matter thereof.*

*Please amend Claim 10 and add new Claims 12 through 14 as follows:*

B2  
Gulr

10. (Amended) An article according to claim 9, wherein the base layer or the intermediate layer contains a hydrogenated hydrocarbon resin.

12. (New) An article according to claim 9, wherein the base layer and the intermediate layer contain a hydrogenated hydrocarbon resin.

B3

13. (New) An article according to claim 9, wherein the outer layer or layers comprises a heat sealable polymer.

14. (New) An article according to claim 9, wherein the polypropylene homopolymer layer comprises a filler.

RECEIVED  
FEB 24 2003  
OFFICE OF PETITION